

Factors affecting surface roughness :-

- Vibration
- Material of the work piece { doesn't deform its shape $\rightarrow$ rigidity }
- Type of machining
- rigidity of the system consists of machine tool, fixture cutting tool
- Type, form, material and sharpness of the cutting tool
- cutting conditions, i.e. feed, speed & depth of cut
- The type of coolant used.

"What are the reasons for controlling surface texture" :-

- To improve the surface life of component
- To improve the fatigue resistance
- To reduce initial wear of parts
- To have a close dimensional tolerance on the parts.
- To reduce frictional wear
- To reduce corrosion by minimizing depth of irregularities
- For good appearance

→

"All the orders of geometrical irregularities"

1) First order

The irregularities caused by inaccuracies in the machine tool itself are called as first order irregularities.

These includes

- a) lack of straightness of guide ways on which the tool must move
- b) surface irregularities due to deformation of work under the action of cutting forces
- c) due to the weight of material itself

2) second order

The irregularities caused due to vibrations of any kind are called second order irregularities. These includes chatter marks on the surface of the parts.

3) Third order

If the machines are perfect and completely free from vibrations, some irregularities are caused by machining itself due to the characteristics of the process. These includes feed mark of the cutting tool.

The fourth order irregularities include those arising from the rupture of the material during the separation of the chip.

→ The irregularities on the surface of the part produce can also be grouped into two parts

- (i) Roughness (or) primary texture
- (ii) waviness (or) secondary texture

Distinguish primary texture and secondary texture

primary Texture

secondary Texture

→ The surface irregularities of small wavelength are called as primary texture (or) roughness

→ The surface irregularities of considerable wavelength of a periodic character are called

Secondary Texture


→ These are caused by direct action of cutting elements on the material like tool feed rate, tool shape (or) some other disturbances such as friction, wear or corrosion

→ These irregularities ^{are} ~~include~~ ~~order~~ and cause due to inaccuracy of slides, wear of guides, misalignment of centers, non linear feed rate, vibrations of any kind

→ The surface profile and the order of irregularities and constitute the micro geometrical errors. These errors include 1st and 2nd order irregularity and constitute macro geometrical errors.

→ The ratio $\frac{l_a}{h_a} < 50$

where, l_a - length along the surface
 h_a - deviation of surface from the ideal one.



→ The ratio of $\frac{l_w}{h_w} > 50$

where,
 l_w - length along the surface
 h_w - deviation of surface from ideal one.



→ It is also called Roughness

→ It is also called waviness

Explain the terms of surface texture:-

a) surface - the surface of a part is confined by the boundary which separates that part from another part of substance/space.

b) Actual surface - This refers to the surface of part which is actually obtain after a manufacturing process.

c) Nominal Surface - It is a theoretical, geometrical perfect shape surface which doesn't exist in practice but is an average of the irregularities that are superimposed on it.

d) profile - It is defined as contour of any section through a surface

Evaluation

Evaluation of surface roughness:-

A numerical assessment of surface finish can be carried out in a number of ways.

These numerical values are obtained with respect to a datum. The following three methods are used for evaluating the primary texture.

a) Average roughness

b) ~~Peak to valley~~ type method peak to valley height method

c) form factor method (or) Bearing curve


(a) Average Roughness:- This method is a statistical method and the following three methods are used for evaluating the avg. roughness.

i) CLA method:- it stands for 'centre line average' (or) arithmetic average.

It is defined as the average values of ordinates from the mean line regardless of the arithmetic ~~sign~~ ~~signs~~ signs.

$$CLA = \frac{A_1 + A_2 + A_3 + \dots}{L} \quad (or)$$

$$CLA = \frac{h_1 + h_2 + h_3 + \dots + h_n}{n}$$



the planimeter is used for finding out the areas. CLA value measure is preferred over RMS. Since the value of the area is measured using planimeter.

ii) RMS method :- it stands for Root mean square method

This method is based on least squares the roughness is measured as the average deviation from the nominal surface

RMS value is defined as square root of arithmetic mean of the values of the squares of the ordinates of the surface measured from a mean line.

It is obtained by setting many equidistance ordinate on


the mean line i.e. $y_1 + y_2 + y_3 + \dots + y_n$ and

when taking the root of the mean of the squared ordinates.

let us assume that the sample length 'L' is divided into 'n' equal parts and $y_1, y_2, y_3, \dots, y_n$ are the heights of the ordinates ~~are~~ erected at those points. Then

$$RMS = \sqrt{\frac{y_1^2 + y_2^2 + y_3^2 + \dots + y_n^2}{n}}$$

$$y_{RMS} = \left[\frac{1}{L} \int_0^L y^2 dL \right]^{1/2}$$




(ii) Ten point height method:— In this method the average diff.

between the five highest peaks and five lowest valleys of surface texture within the sampling length measured from a line parallel to the mean line and not crossing the profile is used to denote the amount of surface roughness.

mathematically it is represented R_z .

$$R_z = \frac{1}{5} [(y_1 + y_2 + y_3 + y_4 + y_5) - (y_6 + y_7 + y_8 + y_9 + y_{10})]$$




www.JntukMaterials.com
This method is relatively simple method. It analyses and measures the total depth of the surface irregularities within the sampling length. But, it doesn't give sufficient information about the surface as no account is taken of frequency of the irregularities and the profile shape.

This method is used to control the cost of finishing for checking the rough machining.

(b) peak to valley height method:-

It measures the maximum depth of surface roughness irregularities over a given sampling length and the largest value of the depth is accepted as the measure of roughness.

The drawback of this method is that it may have same value of t_{max} for two different surface texture in order to overcome the drawback, peak to valley height is defined as the distance b/w a pair of ~~high~~ lines running parallel to the general lay of the ~~case~~ trace position so that the length lying within the peaks at the top is 5% of ~~sample~~ trace length and that within the valleys at the bottom is 10% of the trace length.



(c) Form factor and bearing curve:-

The load carrying area of every surface is often much less than might be thought. This is shown by reference to form factor

The form factor is obtained by measuring the area of the material above the randomly chosen base line in the section and the area of the envelop rectangle therefore the degree of fullness $K = \frac{\text{Area of the metal}}{\text{Area of the rectangle}}$


degree of emptiness $K_p = 1 - K$

bearing area curve:- it is also called Abbott's bearing curve. It is determined by adding the lengths $a, b, c, \dots$ at depths x, y, z below the reference line and indicates the percentage area of bearing which becomes available as the crust area flows away

ISI indication of surface roughness:-

a - Roughness value in micrometers
(or)
Roughness grade [N_1 to N_{12}]

b - the production method, Treatment or coating
c - The sampling length



α - direction of lay

f - other roughness values



e - machining allowance

①.

②. In the measurement of surface roughness heights of 10 successive peaks and troughs was measured from a datum and are 33, 25, 30, 19, 22, 18, 24, 29 & 20 microns if these measurements were obtained on a 10 mm length determine CLA & RMS values of surface roughness

Sol. CLA method =
$$\frac{h_1 + h_2 + h_3 + h_4 + h_5 + h_6 + h_7 + h_8 + h_9 + h_{10}}{10}$$

RMS method =
$$\sqrt{\frac{y_1^2 + y_2^2 + y_3^2 + y_4^2 + y_5^2 + y_6^2 + y_7^2 + y_8^2 + y_9^2 + y_{10}^2}{10}}$$



$$\frac{h_1 + h_2}{2}$$

$$= 20.4$$

$$\frac{1}{2} + \frac{1}{2} \sqrt{1 + 4n}$$

$$= 22.38$$

are as

- a) E-shape stamping
- b) Armature
- c) stylus
- d) cylindrical skid.

construction:-


The stylus is mounted on the armature which is provided at the central limb of an E-shape soft iron head. The outer limbs of the head are provided with two induction coils and the small air gap is left b/w the armature and outer limbs of the head.

Working principle:-

A downward moment of the stylus results in decreasing the air gap of the primary coil and in an equal increase of the air gap at the secondary coil. The impedance of the coils will be change according to the variation of air gap and an additional alternating current flows in the secondary coils whose magnitude is governed by the variation of the impedance of the coil and is proportional to the displacement of the stylus. The position of the stylus controls/modulates the carrier. This method of carrier modulation enables two graphs of the surface texture to be obtained.

A cylindrical skid is provided on a datum and a pickup unit is moved across the test surface by means of a motor and a gear box. This provides different measuring speeds. The maximum length that can be traced is 10 mm. The skid length is made greater than twice the pitch of waviness and a diamond stylus is used having a four sided pyramid shape. The pyramid angle is 90° and the nose radius of the stylus is equal to 2 micrometers. The measuring force of the stylus is 0.1 grams. The vertical magnification can be vary in steps from 1000 - 15000 times.

Optical Comparator:-




Working principle:-

When in these comparators, the fundamental principle of an optical law and instead of a pointer the edge of the shadow is projected on to a curved graduated scale to indicate the comparison measurement if a ray of light OA strikes the mirror gets reflected as ray AB such that

$$\angle OAN = \angle NAB = \theta$$

Now if the mirror is tilted to an angle ' α ' the reflected ray of light is tilted to angle ' 2α ' and optical comparators the mirror is tilted by the measuring plunger moment at the moment is reflected like is recorded as an image on a screen

⊙



In this Comparator the small displacement of the measuring plunger are amplified first by a mechanical system consisting of pivoted mechanical levers the amplified Mechanical Moment is further amplified by a single optical system involving the projection of an image from the fig. We can see that as the plunger is deflected in the vertical directions the lever tilts about the pivoted point. and as the other end of the lever is attached to the mirror the mirror is tilted about the pivot-a and the image of the index is projected on a scale on the inner surface of a ground glass ~~screen~~ and the magnification of the system is given by $= 2 \times \frac{L_2}{L_1} \times \frac{L_4}{L_3}$

Advantages of optical Comparator:-

1. High accuracy : as there are no few moving parts we get high accuracy
2. No parallax error
3. High Magnification
4. optical lever is weightless
5. Illuminated scale

Disadvantages:-

1. Depends on electrical power supply
2. The heat from the lamp, transformers may cause the setting the drift when high magnification used.
3. The system is bulky, it is expensive
4. The instrument is to be use in a dark room
5. Instrument is inconvenient for continuous use because the scale to be use ~~or~~ to be is Through eye piece