




Fig. 31






Fig. 32








Fig. 33



Study the Isometric and Orthographic Views in Figs.34 to 54 and draw the Missing views.




Fig.34





Fig.35






Fig.36






Fig. 37






Fig. 38







Fig. 39






Fig. 40





Fig. 41






Fig. 42






Fig. 43




Fig. 44




Fig. 45

